



PROPERTY INSPECTION REPORT

Important Information Please Read:

For issues identified as 'Imminent Danger' you <u>do not</u> need to contact Home Safe as these issues are referred directly to Peterborough City Council for follow up. We strongly advise that you address these issues immediately in order to safeguard the tenant and your property. Please note that if any report has an 'Imminent Danger' issue within it then Peterborough City Council will follow up all issues in the report regardless of their categorisation, especially those identified as 'Potentially Enforceable'.

For issues identified as 'Potentially Enforceable' and on the proviso that there are no 'Imminent Danger' issues identified in your report, **you are required** to submit evidence to Home Safe (photographs of work done or copies of invoices), within 21 days, illustrating that the identified issue has now been resolved. The link to the evidence submission form can be found in the body of the email that accompanied this report. Please understand that you have a legal responsibility to resolve these identified issues and provide the associated evidence within 21 days of receiving this report.

For issues identified as 'Advisory' you **<u>do not</u>** need to submit evidence or contact either Home Safe or Peterborough City Council but we strongly advise that you resolve the identified issues in a timely manner, in order to avoid such issues becoming more serious.



PCC: Selective Licence Property Inspection (Programme 1)

	Complete
Flagged items	23
Property Address	
Conducted on	
Inspector	

Table of Contents

Disclaimer	3
Flagged items	4
Audit	10
Property Licence Type	10
Property Type	10
Property Interior	10
Habitable Rooms Ground Floor and Below: Living/Dining/Basement Room or Bedroom Etc	
NOTE: For studio apartments please advance to section "Kitchen, Utility Room or Studio Apartme	ent" 10
Habitable Rooms Ground Floor and Below: Living/Dining/Basement Room or Bedroom Etc	
NOTE: For studio apartments please advance to section "Kitchen, Utility Room or Studio Apartme	ent" 1 10
Habitable Rooms Ground Floor and Below: Living/Dining/Basement Room or Bedroom Etc	
NOTE: For studio apartments please advance to section "Kitchen, Utility Room or Studio Apartme	ent" 2 12
Habitable Rooms Ground Floor and Below: Living/Dining/Basement Room or Bedroom Etc	
NOTE: For studio apartments please advance to section "Kitchen, Utility Room or Studio Apartme	ent" 3 14
Kitchen, Utility Room or Studio Apartment	16
Kitchen, Utility Room or Studio Apartment 1	16
Bathroom, WC or En-suite	20
Bathroom, WC or En-suite 1	20
Bathroom, WC or En-suite 2	22
Smoke and Carbon Monoxide Detection	25
Heating type and condition	26
Meters	26
General Safety	27
Occupancy	27
Additional information	28
Sign Off	28
Media summary	29

Disclaimer

The property inspector believes the information contained within this inspection report to be correct at the time of publishing. The inspector or Home Safe does not accept responsibility for any consequences arising from the use of the information herein. The report is based on matters which were observed or came to the attention of the inspector at the time of the inspection and should not be relied upon as an exhaustive record of all possible risks or hazards that may exist or potential improvements that can be made.

Flagged items

No

No

No

Audit / Property Interior / Habitable Rooms Ground Floor and Below: Living/Dining/Basement Room or Bedroom Etc..

NOTE: For studio apartments please advance to section "Kitchen, Utility Room or Studio Apartment" / Habitable Rooms Ground Floor and Below: Living/Dining/Basement Room or Bedroom Etc..

NOTE: For studio apartments please advance to section "Kitchen, Utility Room or Studio Apartment" 1

Q: All areas are free from damp and mould?

(Walls, ceilings, wardrobes etc..)











Photo 10

Photo 5





Photo 7

Photo 9



NOTE: For studio apartments please advance to section "Kitchen, Utility Room or Studio Apartment" 1

Q: Decoration is to an acceptable standard?

Audit / Property Interior / Habitable Rooms Ground Floor and Below: Living/Dining/Basement Room or Bedroom Etc..

Audit / Property Interior / Habitable Rooms Ground Floor and Below:

NOTE: For studio apartments please advance to section "Kitchen, Utility Room or Studio Apartment" / Habitable Rooms Ground Floor and Below:

Living/Dining/Basement Room or Bedroom Etc..

NOTE: For studio apartments please advance to section "Kitchen, Utility Room or Studio Apartment" 2

Q: All areas are free from damp and mould?

(Walls, ceilings, wardrobes etc..)



Photo 21



Photo 22



Photo 23



Photo 24







Audit / Property Interior / Habitable Rooms Ground Floor and Below: Living/Dining/Basement Room or Bedroom Etc..

NOTE: For studio apartments please advance to section "Kitchen, Utility Room or Studio Apartment" / Habitable Rooms Ground Floor and Below:

Living/Dining/Basement Room or Bedroom Etc..

NOTE: For studio apartments please advance to section "Kitchen, Utility Room or Studio Apartment" 2

Q: All ceiling and wall plaster is in sound and secure condition, capable of being decorated with no signs of leaks or possible structural damage?













No





Photo 34





Photo 31



Photo 33



Photo 35

Audit / Property Interior / Habitable Rooms Ground Floor and Below: Living/Dining/Basement Room or Bedroom Etc..

NOTE: For studio apartments please advance to section "Kitchen, Utility Room or Studio Apartment" / Habitable Rooms Ground Floor and Below:

Living/Dining/Basement Room or Bedroom Etc..

NOTE: For studio apartments please advance to section "Kitchen, Utility Room or Studio Apartment" 2

Q: Decoration is to an acceptable standard?











Photo 40

Audit / Property Interior / Habitable Rooms Ground Floor and Below: Living/Dining/Basement Room or Bedroom Etc..

NOTE: For studio apartments please advance to section "Kitchen, Utility Room or Studio Apartment" / Habitable Rooms Ground Floor and Below:

Living/Dining/Basement Room or Bedroom Etc..

NOTE: For studio apartments please advance to section "Kitchen, Utility Room or Studio Apartment" 2

Q: From an internal perspective, any window glazing, frames and furniture are in good working order?

Private & confidential





Audit / Property Interior / Habitable Rooms Ground Floor and Below: Living/Dining/Basement Room or Bedroom Etc..

NOTE: For studio apartments please advance to section "Kitchen, Utility Room or Studio Apartment" / Habitable Rooms Ground Floor and Below:

Living/Dining/Basement Room or Bedroom Etc..

NOTE: For studio apartments please advance to section "Kitchen, Utility Room or Studio Apartment" 3

Q: All areas are free from damp and mould?

(Walls, ceilings, wardrobes etc..)



Audit / Property Interior / Habitable Rooms Ground Floor and Below: Living/Dining/Basement Room or Bedroom Etc..

NOTE: For studio apartments please advance to section "Kitchen, Utility Room or Studio Apartment" / Habitable Rooms Ground Floor and Below:

Living/Dining/Basement Room or Bedroom Etc..

NOTE: For studio apartments please advance to section "Kitchen, Utility Room or Studio Apartment" 3

Q: All ceiling and wall plaster is in sound and secure condition, capable of being decorated with no signs of leaks or possible structural damage? Image: Control of the structural damage is the structural d

Photo 50





Audit / Property Interior / Habitable Rooms Ground Floor and Below: Living/Dining/Basement Room or Bedroom Etc..

NOTE: For studio apartments please advance to section "Kitchen, Utility Room or Studio Apartment" / Habitable Rooms Ground Floor and Below:

Living/Dining/Basement Room or Bedroom Etc..

NOTE: For studio apartments please advance to section "Kitchen, Utility Room or Studio Apartment" 3

Q: Decoration is to an acceptable standard?	No
Audit / Property Interior / Kitchen, Utility Room or Studio Apartment / Kitchen, Utili	ty Room or Studio Apartment 1
Q: All areas are free from damp and mould? (Walls, ceilings, cupboards, wardrobes etc)	No





Audit / Property Interior / Kitchen, Utility Room or Studio Apartment / Kitchen, Utility Room or Studio Apartment 1

Q: All ceiling and wall plaster is in sound and secure condition, capable of being decorated with no signs of leaks or possible structural damage?



Audit / Property Interior / Kitchen, Utility Room or Studio Apartment / Kitchen, Utility Room or Studio Apartment 1

Q: Decoration is to an acceptable standard?







Photo 67

Photo 68

Audit / Property Interior / Bathroom, WC or En-suite / Bathroom, WC or En-suite 1

Q: All areas are free from damp and mould?







Audit / Property Interior / Bathroom, WC or En-suite / Bathroom, WC or En-suite 1

Q: Decoration is to an acceptable standard?



 Audit / Property Interior / Bathroom, WC or En-suite / Bathroom, WC or En-suite 1

 Q: The bathroom has a working extractor fan? If so, please provide a picture clearly showing where the fan is situated?

 Audit / Property Interior / Bathroom, WC or En-suite / Bathroom, WC or En-suite 1

 Q: Bathrooms and shower rooms are free from electrical

Private & confidential

No

No

No

appliances?

Washing machine located in bathroom.



Photo 78

Audit / Property Interior / Bathroom, WC or En-suite / Bathroom, WC or En-suite 2

Q: All areas are free from damp and mould?



Audit / Property Interior / Bathroom, WC or En-suite / Bathroom, WC or En-suite 2

Q: All ceiling and wall plaster is in sound and secure condition, capable of being decorated with no signs of leaks or possible structural damage?





Audit / Property Interior / Bathroom, WC or En-suite / Bathroom, WC or En-suite 2 Q: The bathroom has a working extractor fan? If so, please	Audit / Property Interior / Bathroom, WC or En-suite / Bathroom, WC or En-suite 2	
Q: The bathroom has a working extractor fan? If so, please	Q: Decoration is to an acceptable standard?	No
	Audit / Property Interior / Bathroom, WC or En-suite / Bathroom, WC or En-suite 2	
	Q: The bathroom has a working extractor fan? If so, please provide a picture clearly showing where the fan is situated?	No



Photo 86

Audit / Smoke and Carbon Monoxide Detection

Q: Ground Floor - A working smoke alarm is ceiling mounted and centrally located on this level in the circulation area? (E.g hallways and landings)

No

No



Audit / Smoke and Carbon Monoxide Detection

Q: The property has a sufficient number of working carbon monoxide detectors in appropriate places.

Audit / Additional information

There were no other issues not captured in the main body of the report?



Photo 94

Photo 95

No

Audit	23 flagged
Property Licence Type	
Verified Licence type?	SL - Single Dwelling
Property Type	
Q: Property type?	Flat
Q: Any flats or studio apartment doors that opens onto a common escape route should be equipped with the following? • Smoke seals/Intumescent strips,	
• Self closing device, • Adequate hinges (3 x fire rated)	N/A
The door is to be of solid construction, with working lock, handles, latches and catches. Gaps between the door and frame are to be no greater than 3 mm with no post installation adaptations. E.g DIY installation of a letter box or cat flap. (Fire rated letter boxes are permitted in purpose built flats).	
Q: Any exterior door that does not open onto a common space is in full working order with no signs of damage to the sealant around the door?	Yes
Property Interior	20 flagged
Habitable Rooms Ground Floor and Below: Living/Dining/Basement Room or Bedroom Etc	9 flagged
NOTE: For studio apartments please advance to section "Kitchen, Utility Room or Studio Apartment"	
Habitable Rooms Ground Floor and Below: Living/Dining/Basement Room or Bedroom Etc	2 flagged
NOTE: For studio apartments please advance to section "Kitchen, Utility Room or Studio Apartment" 1	2 nagged
What is the purpose of the room?	Living Room

Room Images









Photo 1

Private & confidential

Room Measurements in meters

3.8 x 2.8m

Q: All areas are free from damp and mould?

(Walls, ceilings, wardrobes etc..)













No

Photo 5



Photo 12

Photo 8

Photo 9

Photo 10

10 - 50% damp or mould evident. If no the issues identified are **Priority** Potentially enforceable Q: All floors are in a safe condition? Yes Q: All ceiling and wall plaster is in sound and secure condition, capable of being decorated with no signs of leaks Yes or possible structural damage? No Q: Decoration is to an acceptable standard? If no the issues identified are Four walls need decorating. Photo 13 Photo 14 Photo 15 Photo 16 Advisory **Priority** Q: From an internal perspective, any window glazing, frames Yes and furniture are in good working order?

Q: Window restrictors are present where required?

E.g. First-floor and above where the window sills are below 800mm in height and the window opens fully (Greater than 100mm) with the potential for a fall from height.

N/A

PLEASE NOTE: Windows on the ground floor or basements would also require a restrictor should a fall be possible to any lower level.		
Select from the following:		N/A - Above 800mm
Q: Any outdoor balcony areas are solid in construction with adequate guarding ? E.g. Solid floor, secure railings, guarding height of 900mm to 1100mm.		N/A
Q: Any interior door is present where it should be, free from damage and in full working order?		Yes
Q: Any sockets present all are in working order?		Yes
Q: Any light switches and light fittings are in full working order and free from damage?		Yes
Q: There is sufficient heating, in good working order with means of temperature control?		Yes
Heating and window type present in this room are		
Radiator, with thermostatic radiator valve fitted UPVC window frames		Double Glazed
Habitable Rooms Ground Floor and Below: Living/Dining/Basement Room or Bedroom Etc NOTE: For studio apartments please advance to section		4 flagged
"Kitchen, Utility Room or Studio Apartment" 2		
What is the purpose of the room?		Bedroom
Room Images		









Photo 20

Room Measurements in meters

3.6 x 4.2m

Q: All areas are free from damp and mould?

(Walls, ceilings, wardrobes etc..)



Photo 28

If no the issue	s identified are			Over 50%	6 damp or mould evident.
Priority				Potent	tially enforceable
Q: All floors ar	e in a safe condi	tion?			Yes
condition, cap		s in sound and s corated with no ?			No
Photo 29	Photo 30	Photo 31	Photo 32	Photo 33	Photo 34



Photo 35

If no the issues identified are

Redecorating required after damp and mould investigation.

Priority

Q: Decoration is to an acceptable standard?











Photo 40

Four walls need decorating.

Water stain to plasterwork. (Possible historical leak)

If no the issues identified are

Priority

Advisory

No

Q: From an internal perspective, any window glazing, frames and furniture are in good working order?



Photo 41

If no the issues identified are	Other, see notes.
Unable to confirm condition of window.	
Priority	Advisory
Q: Window restrictors are present where required?	
E.g. First-floor and above where the window sills are below 800mm in height and the window opens fully (Greater than 100mm) with the potential for a fall from height.	N/A
PLEASE NOTE:	N/A
Windows on the ground floor or basements would also require a restrictor should a fall be possible to any lower level.	
Select from the following:	N/A - Above 800mm
Q: Any outdoor balcony areas are solid in construction with adequate guarding ?	N/A
E.g. Solid floor, secure railings, guarding height of 900mm to 1100mm.	N/A
Q: Any interior door is present where it should be, free from damage and in full working order?	Yes
Q: Any sockets present all are in working order?	Yes
Q: Any light switches and light fittings are in full working order and free from damage?	Yes
Q: There is sufficient heating, in good working order with means of temperature control?	Yes

Heating and window type present in this room are

Radiator, with thermostatic radiator valve fitted	UPVC window frames	Double Glazed

If no the issues identified are

Redecorating required after damp and mould investigation.

Photo 52

Photo 51

Priority

Photo 50

Private & confidential

Habitable Rooms Ground Floor and Below: Living/Dining/Basement Room or Bedroom Etc..

NOTE: For studio apartments please advance to section "Kitchen, Utility Room or Studio Apartment" 3

What is the purpose of the room?

Room Images









Room Measurements in meters

2.6 x 3.6m

Q: All areas are free from damp and mould?

(Walls, ceilings, wardrobes etc..)



Priority







Photo 53





No

(Possible historical leak)

Advisory



Living Room

3 flagged

Q: Decoration is to an acceptable standard?	No
If no the issues identified are	Four walls need decorating.
Priority	Advisory
Q: From an internal perspective, any window glazing, frames and furniture are in good working order?	Yes
Q: Window restrictors are present where required?	
E.g. First-floor and above where the window sills are below 800mm in height and the window opens fully (Greater than 100mm) with the potential for a fall from height.	N/A
PLEASE NOTE:	N/A
Windows on the ground floor or basements would also require a restrictor should a fall be possible to any lower level.	
Select from the following:	N/A - Above 800mm
Q: Any outdoor balcony areas are solid in construction with adequate guarding ?	N/A
E.g. Solid floor, secure railings, guarding height of 900mm to 1100mm.	
Q: Any interior door is present where it should be, free from damage and in full working order?	Yes
Q: Any sockets present all are in working order?	Yes
Q: Any light switches and light fittings are in full working order and free from damage?	Yes
Q: There is sufficient heating, in good working order with means of temperature control?	Yes
Heating and window type present in this room are	
Radiator, with thermostatic UPVC window frames radiator valve fitted	Double Glazed
Kitchen, Utility Room or Studio Apartment	3 flagged
Kitchen, Utility Room or Studio Apartment 1	3 flagged
What is the purpose of the room?	Kitchen

Room Images



Room Measurements in meters

2.3 x 2.6m

Q: All areas are free from damp and mould? (Walls, ceilings,

cupboards, wardrobes etc..)











Photo 59

Photo 60

Photo 62

If no the issues identified are	10 - 50% damp or mould evident.
Priority	Advisory
Q: All floors are in a safe condition?	Yes
Q: The kitchen has adequate work surfaces sealed at edges and to any splash backs?	Yes
Q: The kitchen has adequate dry food storage. All cupboards are securely fixed and all doors and draws are working correctly?	Yes
Q: Any tiling is secure to the wall or floor and in safe condition?	Yes
Q: There is adequate space for a fridge/freezer?	Yes
Q: There is adequate space for a cooker with either a gas supply or electric point?	Yes
Q: Cooking facilities are present and in full working order with no signs of damage that would affect the safe working of the cooking facilities?	Yes
Q: The cooker is located in a position where it can be used safely. It is provided with an adequate adjacent worktop, the area around it is capable of being cleaned, all electrical sockets and switches are located at a suitable distance and there are no flammable items in the immediate area?	Yes

Image of cooking facilities



Photo 63

Q: The kitchen has a fully functional sink with working hot and cold taps and a trapped waste without leakage?	Yes
Q: There is a minimum of six working electrical socket points. Four of which are to be located above counter height in an appropriate location? (Six sockets may not be required in smaller kitchens or where usage is low. In the case of extension lead use a simple rearranging of small appliances may resolve the issue)	Yes
Q: Any light switches and light fittings are in full working order and free from damage?	Yes
Q: There is adequate ventilation? E.g. Externally vented extractor fan, cooker hood extractor.	Yes
What ventilation is present	Cooker extractor hood



Q: There is space for a washing machine or if not another
area in the property has been designated. The property also
has adequate clothes drying facilities. All associated pipe
work is free from leaks?YesQ: All ceiling and wall plaster is in sound and secure
condition, capable of being decorated with no signs of leaks
or possible structural damage?No





If no the issues identified are

Redecorating required after damp investigation.

Damage to ceiling.

Priority

Advisory

No

Q: Decoration is to an acceptable standard?





Photo 67

Photo 68

If no the issues identified are

	Four walls need decorating.	Ceiling needs decorating.
Priority		Advisory
Q: From an internal perspective, any window glazing, frames and furniture are in good working order?		Yes
Q: Window restrictors are present where required? E.g. First-floor and above where the window sills are below 800mm in height and the window opens fully (Greater than 100mm) with the potential for a fall from height. PLEASE NOTE: Windows on the ground floor or basements would also require a restrictor should a fall be possible to any lower level.		N/A
Select from the following:		N/A - Above 800mm
Q: Any outdoor balcony areas are solid in construction with adequate guarding ? E.g. Solid floor, secure railings with gaps no greater than 100mm, guarding height minimum 900mm.		N/A
Q: Any interior door is free from damage and in full working order?		Yes
Q: A floor covering is present	and free from damage?	Yes

Heating and window type present in this room are

UPVC window frames

Double Glazed

Q: The tenant is aware of the location of a fully working water stop tap?	Yes
Bathroom, WC or En-suite	8 flagged
Bathroom, WC or En-suite 1	4 flagged
What is the purpose of the room?	Bathroom

Room Images



Room Measurements in meters

1.2 x 2.5m

Q: All areas are free from damp and mould?







Photo 74

Photo 75

If no the issues identified are	Up to 10% damp or mould evident.
Priority	Advisory
Q: All floors are in sound condition and of a reasonable level. There are no decayed floorboards and any floor covering is intact?	Yes
Q: Any tiling is secure to the wall or floor and in safe condition?	Yes
Q: There is adequate hot and cold water supply to the bathrooms?	Yes
Q: All toilets, baths, showers, sinks and taps are in full working order with undamaged sealant. All waste connections are clear and free from leaks?	Yes
Q: All ceiling and wall plaster is in sound and secure condition, capable of being decorated with no signs of leaks or possible structural damage?	Yes

Q: Decoration is to an acceptable standard?

If no the issues identified are	Ceiling needs decorating.
Priority	Advisory
Q: From an internal perspective, any window glazing, frames and furniture are in good working order?	N/A
Q: Window restrictors are present where required? E.g. First-floor and above where the window sills are below 800mm in height and the window opens fully (Greater than 100mm) with the potential for a fall from height. PLEASE NOTE: Windows on the ground floor or basements would also require a restrictor should a fall be possible to any lower level.	N/A
Select from the following:	N/A - No window
Q: Any outdoor balcony areas are solid in construction with adequate guarding ? E.g. Solid floor, secure railings with gaps no greater than 100mm, guarding height minimum 900mm.	N/A
Q: Any interior door is free from damage and in full working order?	Yes
Q: The bathroom has a working extractor fan? If so, please provide a picture clearly showing where the fan is situated?	No
If no the issues identified are	No ventilation is available. (No openable window or extraction unit)
Priority	Advisory
Q: Any light switches and light fittings are in full working order and free from damage?	Yes
Q: A floor covering is present and free from damage?	Yes

Q: Bathrooms and shower rooms are free from electrical appliances?

Washing machine located in bathroom.



Photo 78

Priority	Potentially enforceable
If no the issues identified are	Electrical appliances present in bathroom/shower room
	Remove all electrical appliances from bathroom/shower room.
Additional Landlord Information:	This is unless you can provide a small works report from a qualified electrician within 21 days which states the electrical appliances are safe in the current location. E.g. satisfactory RCD on the consumer unit, correct Zone positioning etc
Q: There is sufficient heating, in good working order with means of temperature control? (Mark N/A for small areas unless heating is present, any heating that is present should be in good working order)	N/A
Bathroom, WC or En-suite 2	4 flagged
What is the purpose of the room?	WC

Room Images



Photo 79

Room Measurements in meters

0.9 x 1.3m

Q: All areas are free from damp and mould?



If no the issues identified are	Up to 10% damp or mould evident.
Priority	Advisory
Q: All floors are in sound condition and of a reasonable level. There are no decayed floorboards and any floor covering is intact?	Yes
Q: Any tiling is secure to the wall or floor and in safe condition?	N/A
Q: There is adequate hot and cold water supply to the bathrooms?	N/A
Q: All toilets, baths, showers, sinks and taps are in full working order with undamaged sealant. All waste connections are clear and free from leaks?	N/A
Q: All ceiling and wall plaster is in sound and secure condition, capable of being decorated with no signs of leaks or possible structural damage?	No





Photo 83

If no the issues identified are

Damag	ge to ceiling.	Cracks to plasterwork in wall(s)/ceiling.	Water stain to plasterwork. (Possible historical leak)
Priority			Advisory
Photo 84 Ph	noto 85		
Q: Decoration is to	o an accepta	ble standard?	No

If no the issues identified are

	Four walls need decorating.	Ceiling needs decorating.
Priority		Advisory
Q: From an internal perspection and furniture are in good wor	ve, any window glazing, frames king order?	Yes
Q: Window restrictors are pre E.g. First-floor and above whe 800mm in height and the wind 100mm) with the potential for PLEASE NOTE: Windows on the ground floor require a restrictor should a f level.	re the window sills are below dow opens fully (Greater than r a fall from height. or basements would also	N/A
Select from the following:		N/A - Above 800mm
Q: Any outdoor balcony areas are solid in construction with adequate guarding ? E.g. Solid floor, secure railings with gaps no greater than 100mm, guarding height minimum 900mm.		N/A
Q: Any interior door is free fro order?	om damage and in full working	Yes
Q: The bathroom has a workir provide a picture clearly show	ng extractor fan? If so, please ving where the fan is situated?	No



If no the issues identified areNo ventilation is available. (No openable window or extraction unit)PriorityAdvisoryQ: Any light switches and light fittings are in full working order and free from damage?YesQ: A floor covering is present and free from damage?YesQ: Bathrooms and shower rooms are free from electrical appliances?Yes

Q: There is sufficient heating, in good working order with means of temperature control? (Mark N/A for small areas unless heating is present, any heating that is present should be in good working order)	N/A
Smoke and Carbon Monoxide Detection	2 flagged
Where the property is of open plan layout, the following are present.	
1: Interlinked smoke detection system on all floors plus heat detection in any kitchen area. (These can be interlinked via WIFI or Hardwired)	N/A
2: An accessible escape window where practicable, in an appropriate location.	
NOTE: Open plan layouts refer to houses and flats where there is no physical separation between the kitchen and the main escape route from the property.	
Q: Basement Floor - A working smoke alarm is ceiling mounted and centrally located on this level ?	N/A
Q: Ground Floor - A working smoke alarm is ceiling mounted and centrally located on this level in the circulation area ? (E.g hallways and landings)	No



If no the issues identified are	The smoke detector is incorrectly positioned.
Needs relocating to ceiling.	
Priority	Potentially enforceable
Q: First Floor - A working smoke alarm is ceiling mounted and centrally located on this level in the circulation area ? (E.g hallways and landings)	N/A
Q: Second Floor - A working smoke alarm is ceiling mounted and centrally located on this level in the circulation area ? (E.g hallways and landings)	N/A
Q: Third Floor & Above - A working smoke alarm is ceiling mounted and centrally located on this level in the circulation area ? (E.g hallways and landings)	N/A
Q: The property has a sufficient number of working carbon	No

monoxide detectors in appropriate places.	
If no the issues identified are	Missing carbon monoxide detector.
Priority	Potentially enforceable
Heating type and condition	
Q: Hot water and heating system are in good working order and has a means of temperature control?	Yes
Hot water and Heating system present	Gas central heating

Image of any Gas boiler, immersion heater or under sink water heater.



Meters Q: The electricity supply is accessible to inspect and adequately earthed or has an RCD? Yes (Electricity supply: AKA Consumer unit / fuse box)

Photo of fuse box



Photo 89

Q: The electric meter is accessible to inspect with no signs of being tampered with, is fixed securely but not easily accessible to children/vulnerable adults?

Yes

Photo of electric meter



Photo 90



Q: The gas meter is accessible to inspect and has no signs of being tampered with?

Yes

Photo of Gas meter



Photo 92

Q: The property has secondary earth bonding to gas and water pipes?

Photo of earth bonding



Photo 93

General Safety

Q: The property has sufficient artificial or natural lighting?	Yes
Q: The property has an adequate provision of bins and recycling boxes/bags for correct waste disposal as per Local Authority policies and procedures?	Yes
Q: The property shows no signs of pest or vermin infestation?	Yes
Q: If the property has a burglar alarm system it is in full working order and the tenant has the necessary information to operate the alarm? (Mark as N/A if the property does not have one)	N/A
Q: If the property has a TV aerial, it is in full working order along with any of its connections?	Yes
Q: The Tenant has been provided an alley gate key if applicable?	N/A
Q: The property has at least one window key that works all window locks?	Yes
Occupancy	
Q: Number of adults occupants?	1
Q: Number of child occupants?	0

There are no signs of overcrowding?	Yes
No signs of excessive hoarding.	Yes
There were no Child Sexual Exploitation (CSE), children or adult safeguarding issues, or other concerns identified or suspected at the property.	Yes
Additional information	1 flagged
There were no other issues not captured in the main body of the report?	No





Details of any other issues not captured in the main body of the report.

Due to the amount of damp and mould throughout the property, it has been upgraded to potentially enforceable. Tenant has reported a major leak from guttering.

Images of any other issues not captured within the main body of the report.







Media summary



Photo 1



Photo 3





Photo 4









Photo 6



Photo 8









Photo 10



Photo 12







Photo 14



Photo 16



Photo 17



Photo 19



Photo 18



Photo 20





Photo 23





Photo 24





Photo 27





Photo 28






Photo 30



Photo 32





Photo 35





Photo 36







Photo 38



Photo 40





Photo 43





Photo 44



Photo 45



Photo 47



Photo 46



Photo 48





Photo 51





Photo 52





Photo 55





Photo 56







Photo 59



Photo 58



Photo 60







Photo 62



Photo 64





Photo 67





Photo 68



Photo 69



Photo 71



Photo 70



Photo 72









Photo 74



Photo 76









Photo 78



Photo 80









Photo 82



Photo 84









Photo 86



Photo 88





Photo 91





Photo 92



Photo 93



Photo 95



Photo 94



Photo 96



